

REMEMBER P. A. S. S.

Pull - Aim - Squeeze - Sweep if you have to fight a fire with a fire extinguisher.

It Happened...

On October 6, 1989, two fifty ton locomotives and the loaded cars they were pulling derailed. This caused extensive damage to the equipment, trolley and railbed. A short circuit of the trolley wire caused a fire inside the locomotive rectifier. The fire was extinguished after an hour by using eight fire extinguishers

On April 11, 1990, a fire occurred in a transformer located in the track entry. The fire was discovered when the section belt stopped. Six fire extinguishers were utilized until water could be directed to the fire area.

On June 18, 1990, a wedged shaped rock lodged between the belt and the take-up roller causing the belt to slip. This caused a fire at the head pulley and the second drive roller. Fire fighting activities lasted nearly an hour. Fire extinguishers were used while the fire hose was retrieved and installed.



Target Board for storing fire extinguishers and small equipment in a highly visible and accessible location.

Best Practices Fire Protection

Card No. BPFP-3



FIRE
EXTINGUISHERS

FIRE EXTINGUISHERS are often the initial resource for fire fighting activities. These devices, when used in the early stages of a fire, can provide additional time until fire fighting resources arrive at the scene. Fire extinguishers need to be stored in a visible location and be readily accessible.

LOCATIONS

Working Sections	Diesel Equipment
Track Locomotives	Electrical Installations
Self-propelled Mantrips	Fuel Storage Locations
Personnel Carriers	Oil Storage Locations
Welding and Cutting	Wooden Doors with Powerlines

- **ALWAYS** maintain fire extinguishers in working order.
- **ALWAYS** keep fire extinguishers well marked and readily accessible.
- **ALWAYS** remove extinguishers found without inspection tags and have them checked.
- **ALWAYS** have extinguishers serviced by a trained person or qualified contractor.
- **ALWAYS** locate fire extinguishers upwind of potential fire areas.
- **NEVER** put a discharged fire extinguisher back until it has been serviced and recharged.
- **NEVER** allow unqualified personnel to recharge a fire extinguisher.
- **NEVER** keep a rusty fire extinguishers in service.

U.S. Department of Labor
Mine Safety and Health Administration
J. Davitt McAteer, Assistant Secretary